


<b>Title of Change:</b>	MPL33 Case Outline Lead Length "L" and Lead DAP Length "G" Dimension Tolerance Change
<b>Effective date:</b>	01 Apr 2022
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:Godfrey.Valles@onsemi.com">Godfrey.Valles@onsemi.com</a>
<b>Type of notification:</b>	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.
<b>Change Category:</b>	Documentation
<b>Change Sub-Category(s):</b>	Datasheet/Product Doc change

**Sites Affected:**

<b>onsemi Sites</b>	<b>External Foundry/Subcon Sites</b>
None	None


**Description and Purpose:**

Changed Lead Length (dimension L) and Lead DAP Length (dimension G) to 0.40 +/- 0.10 mm (using JEDEC Standard Tolerance) of 511DR Case Outline. For Reference Case Outline/Dimension Alignment.




*Old Case Outline Drawing:*

E3	0.15	0.20	0.25
e	0.65 BSC		
G	0.40	0.45	0.50
L	0.40	0.45	0.50
Ø	0	-	12



DOCUMENT NUMBER:	98AON13650G	PAGE 1 OF 1
DESCRIPTION:	WDFN8 3.3x3.3, 0.65P	



**List of Affected Standard Parts:**

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

FDMC86106LZ-P	FDMC3612	FDMC86106LZ
FDMC86116LZ	FDMC86244	FDMC8015L
FDMC8327L	FDMC4435BZ	FDMC0310AS-F127
FR014H5JZ	FDMC8882	FDMC7696
FDMC7678	FDMC6675BZ-P	FDMC6675BZ
FDMC4435BZ-F127	FDMC8622	

Appendix A: Changed Products

PCN#: PB24618X  
Issue Date: Mar 29, 2022

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
FDMC3612				
FDMC86244				
FDMC8015L				
FDMC8327L				
FDMC4435BZ				
FR014H5JZ				
FDMC8882				
FDMC7696				
FDMC7678				
FDMC6675BZ				
FDMC8622				
FDMC86116LZ				